

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

RECEIVED
EPA REGION VI
95 FEB 16 AM 7:37
SUPERFUND MANAGEMENT
BRANCH

SITE NAME : LIBERTY FORGE, INC.

LOCATION : LIBERTY, TX

SITE NUMBER: TXD988072567

SURVEY DATE: 1990 INSPECTED BY: STATE (FIT) TAT OTHER: _____

LABORATORY : CLP EPA OTHER N/A

RECEIVED FROM: Betty Williamson

DATE RECEIVED: 02/08/95

SAMPLE TYPE(s): N/A

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological N/A

FOLLOW UP (Y/N):

<u>N</u>	(Re) Sampling Requested	<u>N</u>	Locate Drinking Water Sources
<u>N</u>	Further Action is URGENT	<u>N</u>	Keep Site Active ("N"=No Further Action)
		<u>Y</u>	Concur with Report Recommendations

SUMMARY:

According to the attached information, the site is an active steel forge/fabrication facility that began operations in 1975. The facility has no inactive waste management units. All waste units on the site are active and continue to recycle and stockpile facility generated wastes. A review of Surface Water Use Maps indicated that there are no permitted uses of surface water within 15 miles of the site's Probable Point of Entry (PPE). The TNRCC has been actively monitoring solid waste activities at the site.

RECOMMENDATION:

Based on the available information, it appears that the potential for ground or surface water contamination from this site is very unlikely at this time.

Concurrence:

Edgar A. Jiffon

2/13/95

Hillol K. Ray
ENGINEER/REVIEWER

02/13/95